5.0

BRAKE NO

Comment: NC BRAKE

Bend as per Dwg D3781

Job Number: 40734 Part Number: D37811 Job Number: Seq. #: Machine Or Operation: Description: SMALL FAB 1 SMALL & MEDIUM FAB RESOURCE 1 6.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 1-counter sink holes as per dwg D3781 7.0 QC5 INSPECT WORK TO CURRENT STEP ENGINEERING APPROVAL Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING RESOURCE #1 HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 9.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION MS20426AD34 10.0 RIVET Comment: Qty.: 10.0000 Each(s)/Unit Total: 100.0000 Each(s) RIVET batch: 11.0 Nutplate Comment: Qty.: 5.0000 Each(s)/Unit 50.0000 Each(s) Total: Nutplate 04 068 186 batch: 12.0 SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 881112 1- assemble nut plate as per dwg D3781 13.0 QC5 Comment: INSPECT WORK TO CURRENT STEP PLEAS TO ENGINEERING FOR ENGINEERING USE ONLY B. 11.13

STREAMER INC. INC. UNIT.

APPROVAL

Linda Lacelle

Process Sheet

Justomer: CU-DAR001 Dart Helicopters Services

Drawing Name: SUPPORTING PLATE

Job Number: 40734

Part Number: D37811

Job Number:



Seq. #:

Machine Or Operation:

Description:

14.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

Acrotex

FINAL INSPECTION/W/O RELEASE

15.0

QC21



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



POSITIVE RECALL

DATE


RELL

FOR FIT & FUNCTION PURPOSES ONLY. SHIP TO DAVID SHEPHERD. NOT FOR STOCK.


PLEASE RETURN ALL ISSUED DATA TO ENGINEERING


FOR ENGINEERING USE ONLY

. THE EAST MEETING GES CHIT.



	*	





3

PLEASE RETURN ALL ISSUED DATA TO ENGINEERING 1208.11.13

FOR ENGINEERING USE ONLY

DETAIL B SCALE 2X, 5 PL



DESIGN	16	DART AEROSPACE LTD				
DRAWN	4	HAWKESBURY, ONTARIO, CANADA				
CHECKED		DRAWING NO.	REV. B			
MFG. APPR.		D3781	SHEET 2 OF 3			
APPROVED DE APPR.		TITLE	SCALE			
		CUSHION ASSEMBLY	NTS			
DATE 08.0	7.15	COPYRIGHT © 2008 BY DART AEROSE THIS DOCUMENT IS PRINATE AND CONFIDENTIAL AND IS SUPPLIED ON THE E NOT TO BE USED FOR ANY PURPOSE OR COMMISSIONATE TO IN- WASTERS PERMASSION FROM DART AEROSPACE.	XPRESS CONDITION THAT IT IS NY OTHER PERSON WITHOUT			

13 -

TENER OF THE PARTY OF THE PARTY

Description:		C -1 A						
Inspection Dwg		Description: Suppost in C PLATE						
mspection Dwg	:D3781 Rev:	-		Page 1 of 1				
	TENE SIN LI				1			
	FIRST	ARTICLE IN First Artic		Proto		The state of the s		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments		
\$ 1098	1,005001	,100	×					
106. B	1005 - 200+	.303	×					
1.500	4/- ,010	1.501	×					
2,61	1/- ,030	7.67	*					
2.859	1/010	€38.6	de					
5.500	1/010	5,500	×					
9.500	7010	9,500	×					
080.	7010	180.	*					
	-							
			46.1					
Measured by:	IB A	udited by:	5	Pi	rototype Approv	val: A-/		

					-
					•